

NEW INN FARMHOUSE, STOWE

The Front of the building was photographed circa 1900



1 This can be compared with a photograph taken in December 2001.



A line drawing by J C Nattes from around 1809 shows the interior of the courtyard.



2 This is the current condition of the courtyard taken from a similar position.





3 Inner elevation of Rear Range – coach house – before roof collapsed



4 Inner elevation of North East Range – Brewhouse and entrance to Dairy



5 External view of South West Range of Stables

