Buckinghamshire County Council - Rights of Way
Summary of Maintenance Carried Out
Between April 2014 and February 2015

TYPE	DESCRIPTION	Aprl 14 - Mar 15	Aprl- Feb 15
Alignment	Path Off Line - resolved issue	6	12
Clearance	Clearance - carried out-jobs/km	133km	151km
Bridge	Installed or repaired	39	48
Finger/post	Installed or repaired	149	199
Fly Tipping	Fly Tipping - removed	10	4
Gate	Gate repaired or installed	91	88
Intimidation + animal	Intimidation - resolved	13	31
Intimidating sign	Misleading Sign - removed	3	6
Obstruction - resolved	Barbed wire	6	4
Obstruction - resolved	Barrier - Fencing, wall or other	71	123
Obstruction - resolved	Electric fence	10	19
Obstruction - removed	Fallen Tree	236	174
Obstruction - resolved	Locked Gate	9	17
Obstruction - resolved	Ploughing and Cropping	107	130
Other	Delivery of materials	27	40
Other	Miscellaneous issues resolved	35	47
Stile	Installed or repaired	163	198
Stile	Stile To Gap	15	29
Stile	Stile To KG	61	74
Stile	Stile To PG	36	56
Terrain	Bank Steps	5	12
Terrain	Path Surface problem resolved	44	83
Waymark Post	Installed/Repaired	126	123
Authorisation	New Structure HA80 sec 147	2	2
Issues Completed	Since 1st April 2015		1816
Volunteer Hours	The Chiltern Society	1750	1122
Volunteer Hours	RA Only		300
Improvements	To aid mobility access	191	264
5% Survey Results	Paths Rated easy to use	84%	64%
5% Survey Results	Structures rated easy to use	94%	90%
5% Survey Results	Routes with Roadside Signs	96%	96%
Number on Database	No. of issues os 31/03/12	799	
Number on Database	No. of issues os 31/03/13	1150	
Number on Database	No. of Issues os 31/03/14	1085	
Number on Database	No. of Issues os 31/03/15	1423	
Number on Database	No. of Issues os 29/03/16		1455
% of issues in targ time	Enforcement issues	76%	72%

Chiltern Society Jobs

Completed	Type	
upto 29 th Feb 2016	Clearance direct from BCC	131 jobs/28km
	Miscellaneous Jobs	6
	Waymarking and signs	80
	Gates Repaired and installed	41
	Bank Steps	4
	Stiles replaced and repaired	57
	Trees removed	43
	1122 hours	362 jobs completed