

**Buckinghamshire County Council - Rights of Way  
Summary of Maintenance Carried Out  
Between 1/04/15 and 31/03/17**

TYPE	DESCRIPTION		
		April 15 - Mar 16	April 16- Mar 17
Alignment	Path Off Line - resolved issue	9	55
Clearance	Clearance - carried out-jobs/km	159km	135km
Bridge	Installed or repaired	61	82
Finger/post	Installed or repaired	233	139
Fly Tipping	Fly Tipping - removed	7	17
Gate	Gate repaired or installed	97	95
Intimidation + animal	Intimidation - resolved	30	28
Intimidating sign	Misleading Sign - removed	6	10
Obstruction - resolved	Barbed wire	4	17
Obstruction - resolved	Barrier - Fencing, wall or other	117	211
Obstruction - resolved	Electric fence	20	30
Obstruction - removed	Fallen Tree	193	277
Obstruction - resolved	Locked Gate	19	27
Obstruction - resolved	Ploughing and Cropping	133	131
Other	Delivery of materials	44	45
Other	Miscellaneous issues resolved	44	45
Stile	Installed or repaired	217	226
Stile	Stile To Gap	32	17
Stile	Stile To KG	76	56
Stile	Stile To PG	62	79
Terrain	Bank Steps	14	19
Terrain	Path Surface problem resolved	74	117
Waymark Post	Installed/Repaired	148	171
Authorisation	New Structure HA80 sec 147	2	6
Issues Signed off	Since 1st April 2015	2197	2439
Volunteer Hours	The Chiltern Society	1368	1717
Volunteer Hours	RA Only	445	698
Improvements	To aid mobility access	257	247
5% Survey Results	Paths Rated easy to use	64%	66%
5% Survey Results	Structures rated easy to use	90%	97%
5% Survey Results	Routes with Roadside Signs	95%	89%
Number on Database	No. of issues os 31/03/12	799	
Number on Database	No. of issues os 31/03/13	1150	
Number on Database	No. of Issues os 31/03/14	1085	
Number on Database	No. of Issues os 31/03/15	1423	
Number on Database	No. of Issues os 31/03/16	1531	
Number on Database	No. of Issues os 31/03/17		1114
% of issues in targ time	Category C issues on Matrix	72%	72%
% of issues in targ ave.	% Enf issues in targ time in mth	no data	73%

**Above includes**

Clearance direct from BCC

Miscellaneous Jobs

Waymarking and signs

Gates Repaired and installed

Bank Steps

Stiles replaced and repaired

Trees removed

Total Jobs

Hours

**Volunteer Jobs Completed**

136 jobs/29km 180 jobs/43km

8 17

105 121

53 67

5 7

74 75

47 69

428 jobs 536 jobs

1813 hours 2415 hours